

Annex I

No. 0H181116.DTQQ07

Test Report no. SCC(18)-799-11-18-LVD, SCC(18)-799-11-19-EMC



Model(s):

EPS-B1-0D20AA-A000	DS1P-01AS
EPS-B1-0D40AA-A000	DS1P -02AS
EPS-B1-0D75AA-A000	DS1P -04AS
EPS-B1-0001AA-A000	DS1P -08AS
EPS-B1-01D5AA-A000	DS1P-10AS
EPS-B1-02D2AA-A000	DS1P-15AS
EPS-B1-0003AA-A000	DS1P-20AS
EPS-B1-04D5AA-A000	DS1P-30AS
EPS-B1-02D2BA-A000	DS1P-45AS
EPS-B1-0003BA-A000	DS1E-01AS
EPS-B1-04D5BA-A000	DS1E-02AS
EPS-B1-05D5BA-A000	DS1E-04AS
EPS-B1-07D5BA-A000	DS1E-08AS
EPS-B1-0011BA-A000	DS1E-10AS
EPS-B1-0015BA-A000	DS1E-15AS
EPS-B1-0022BA-A000	DS1E-20AS
EPS-B2-0D10AA-A000	DS1E-30AS
EPS-B2-0D20AA-A000	DS1E-45AS
EPS-B2-0D40AA-A000	
EPS-B2-0D75AA-A000	
EPS-B2-0001AA-A000	
EPS-B2-01D5AA-A000	
EPS-B2-02D2AA-A000	